

File Original and First Copy with
Department of Ecology
Second Copy — Owner's Copy
Third Copy — Driller's Copy

WATER WELL REPORT

STATE OF WASHINGTON

Application No

Permit No

(1) OWNER: Name B.J. SUSE Address 2060 E. STRAWBERRY PT. Rd 98277
(2) LOCATION OF WELL: County 1 SLAND NW 1/4 SE 1/4 Sec 35 T33 N. R2E W.M.
Reading and distance from section or subdivision corner

(3) PROPOSED USE: Domestic ☒ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(4) TYPE OF WORK: Owner's number of well (if more than one) _____
New well ☒ Method: Dug ☐ Bored ☐
Deepened ☐ Cable ☒ Driven ☐
Reconditioned ☐ Rotary ☐ Jetted ☐

(5) DIMENSIONS: Diameter of well 6 inches.
Drilled 149 ft Depth of completed well 149 ft.

(6) CONSTRUCTION DETAILS:

Casing installed: 6" Diam. from 0 ft. to 144 1/2 ft.
Threaded ☐ " Diam. from _____ ft. to _____ ft.
Welded ☒ " Diam. from _____ ft. to _____ ft.

Perforations: Yes ☐ No ☒

Type of perforator used _____
SIZE of perforations _____ in. by _____ in.
perforations from _____ ft. to _____ ft.
perforations from _____ ft. to _____ ft.
perforations from _____ ft. to _____ ft.

Screens: Yes ☒ No ☐

Manufacturer's Name Johnson
Type STAINLESS Model No. _____
Diam. 6 Slot size 1/4 from 149 ft. to 149 ft.
Diam. _____ Slot size _____ from _____ ft. to _____ ft.

Gravel packed: Yes ☐ No ☒ Size of gravel _____
Gravel placed from _____ ft. to _____ ft.

Surface seal: Yes ☒ No ☐ To what depth? 18 ft.

Material used in seal CLAY
Did any strata contain unusable water? Yes ☐ No ☒
Type of water? _____ Depth of strata _____
Method of sealing strata off _____

(7) PUMP: Manufacturer's Name _____

Type: Sub HP _____

(8) WATER LEVELS: Land-surface elevation _____

Static level 100 ft. below top of well Date May 88

Artesian pressure _____ lbs. per square inch Date _____

Artesian water is controlled by _____ (Cap, valve, etc.)

(9) WELL TESTS:

Drawdown is amount water level is lowered below static level

Was a pump test made? Yes ☐ No ☒ If yes, by whom? _____

Yield: _____ gal./min. with _____ ft. drawdown after _____ hrs.

" " " " " "

" " " " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test _____

Bailer test 0 gal./min. with 36 ft. drawdown after 4 hrs.

Artesian flow _____ g.p.m. Date _____

Temperature of water _____ Was a chemical analysis made? Yes ☐ No ☒

(10) WELL LOG:

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
GRAVELY	0	7
HARD PAN	7	15
GRAVELY	15	48
CLAY	48	80
HARD PAN	80	138
FINE SOUPY SAND	138	144
WATER SAND M.I.K	144	149

Work started _____ 19 _____ Completed MAY 19 88

WELL DRILLER'S STATEMENT:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME W. H. DIBBY DRILLERS
(Person, firm, or corporation) (Type or print)

Address oak harbor 98277

[Signed] Kevin John
(Well Driller)

License No. 129 Date MAY 19 88

(USE ADDITIONAL SHEETS IF NECESSARY)



WASHINGTON STATE
DEPARTMENT OF
ECOLOG Y

Well Tagging Form

Unique Well Tag No: APR788

RECORD VERIFICATION (check ☒ one)

- ☒ Well Report available (please attach this form to the well report and submit it to the Ecology Regional Office near you)
- ☐ Verification inconclusive
- ☐ Well Report not available

WELL OWNERSHIP IF DIFFERENT FROM WELL REPORT

Name: Strawberry Point Water Association

Street Address: 1950 STICK POINT LN

City: OAK HARBOR

State: WA

WELL LOCATION IF DIFFERENT FROM WELL REPORT

Well Address: Stick Point Lane

City: Oakharbor

County: Island

T. 33N R. 02E W.M. Sec. 36 NW 1/4 of the SW 1/4

FOR AGENCY USE ONLY

Latitude: 48 18.08067

Longitude: 122 30.41791

Elevation at land surface 132 feet meters (circle one)

Additional Information, if available:

- ☐ Location marked on topographic map (please attach)
- ☐ Location marked on air photo (please attach)

- ☒ GPS
- ☐ Topographic Map
- ☐ Survey
- ☐ Computer generated
- ☐ Digital Altimeter
- ☐ Topographic Map
- ☒ Other: Computer Generated from
DEM and GPS XY Coordinates

Tag placed and well
GPS'd by:



FOR AGENCY USE ONLY

WELL CHARACTERISTICS

Physical Description of well (size of casing, type of well, housing, etc.)

6 Inch Casing In Well House

Location of Well Identification Tag:

Strapped To Well Casing

Was supplemental tag needed for easy of identifying well?

☐

Yes

☒

No

If yes, where was tag placed? _____

D	C	B	A
E	F	G	H
● M	L	K	J
N	P	Q	R

SECTION: 33N/02E-36

COMMENTS: _____

FOR ECOLOGY WATER RESOURCES PROGRAM ONLY

Water Right # _____

Date Issued: _____

Circle One:

Application

Permit

Certificate

Claim

Exempt

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

WATER WELL REPORT

State of Washington

IC Site ID: 487

Start Card: 6940

Water Right:

Unique Well ID

(1) OWNER: Name: B J. Suse Address: 2560 E. Strawberry Point Road Oak Harbor WA, 98277

(2) LOCATION OF WELL: Island: Whidbey Township/Range-Section: 33N/02E-36M Parcel Number: R23336-181-0130

(2a) Well Address PWS-ID: 01564A Source: 1 PWS-Name: Strawberry Point Water Association

(3) PROPOSED USE: Domestic

(4) TYPE OF WORK: Owner's Well Number (if more than one): 1
New Well Method: Cable Tool

(5) DIMENSIONS: Diameter of Well: 6 inches.
Drilled: 149 feet. Depth of Completed Well: 149 ft.

(6) CONSTRUCTION DETAILS:
Casing Installed: Diam. (in) from to (ft)
6 0 144.5

Screens: Type Zone Diam Slot from to (ft)
Stainless Steel 1 6 0.14 144 149

Surface seal:
Material: Clay or Cuttings To depth: 18 ft.

(7) PUMP: Type: Submersible Horsepower:

(8) WATER LEVELS: 1 Land-surface elevation (MSL): 185 ft.
Avg WL Elevation: -4 Calc'd Elev: 96 ft.
Earliest Level: 100.00 ft. below toc Date: 5/1/1988
Lastest Level: 100.00 ft. below toc Date: 5/1/1988
Average Level: 100.00 ft. below toc Average Date: 5/1/1988

(9) WELL TESTS:
Type Yield Drawdown After Date
Bailer 8 gpm 36 feet 4 hours 5/1/1988

(10) WELL LOG DESCRIPTION:

Material	From BGS	From MSL	Thick
Gravely	0	96	7
Hardpan	7	89	8
Gravely	15	81	33
Clay	48	48	32
Hardpan	80	16	58
Fine Soupy Sand	138	-42	6
Water Sand Mix	144	-48	5
TD	149	-53	

Work Completed: 5/1/1988 TD Elev: -53 ft. MSL

WELL CONSTRUCTOR CERTIFICATION:

Name: Whidbey Drillers
Address: 1143 W. Ft. Nugent Rd, OH, WA 98277
Contractor's
Registration Number: WHIDBWD289

Remarks: TRS changed from 33N/02E-35K after Parcel Check.

Location Source: North: 479212 Latitd: 48° 18' 3.12"
Parcel R23336-181-0130 East: 1593269 Longit: 122° 30' 20.2
Max CL: 19 Generated by the Island County
Max NO3: 0.25 Hydrogeologic Database: 8/1/2006

Disclaimer: Data presented has been collected from a variety of sources.
Island County makes no guarantee as to the validity or accuracy of this data.
Please report any errors to the Island County Hydrogeologist

File Original and First Copy with
Department of Ecology.
Second Copy - Owner's Copy
Third Copy - Driller's Copy

WATER WELL REPORT

STATE OF WASHINGTON

Application No

Permit No

(1) OWNER: Name B.J. SUSE Address 2560 E. STRAWBERRY PT. RD 9827

(2) LOCATION OF WELL: County ISLAND NW 1/4 SE 1/4 Sec 35 T33 N. R2E W.M

Bearing and distance from section or subdivision corner

(3) PROPOSED USE: Domestic ☒ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(4) TYPE OF WORK: (Owner's number of well (if more than one))
New well ☒ Method: Dug ☐ Bored ☐
Deepened ☐ Cable ☒ Driven ☐
Reconditioned ☐ Rotary ☐ Jetted ☐

(5) DIMENSIONS: Diameter of well 6 inches.
Drilled 149 ft Depth of completed well 149 ft.

(6) CONSTRUCTION DETAILS:

Casing installed: 6 " Diam. from 0 ft. to 149 1/2 ft.
Threaded ☐ " Diam. from ft. to ft.
Welded ☒ " Diam. from ft. to ft.

Perforations: Yes ☐ No ☒

Type of perforator used...
SIZE of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

Screens: Yes ☒ No ☐

Manufacturer's Name Johnson
Type STAINLESS Model No
Diam 6 Slot size 19 from 149 ft. to 149 ft.
Diam. Slot size from ft. to ft.

Gravel packed: Yes ☐ No ☒ Size of gravel ft.
Gravel placed from ft. to ft.

Surface seal: Yes ☒ No ☐ To what depth? 18 ft.
Material used in seal CLAY
Did any strata contain unusable water? Yes ☐ No ☒
Type of water? Depth of strata
Method of sealing strata off

(7) PUMP: Manufacturer's Name Sub H.P.

(8) WATER LEVELS: Land-surface elevation 185 ft. above mean sea level
Static level 100- ft. below top of well Date May 88
Artesian pressure lbs. per square inch Date
Artesian water is controlled by (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? Yes ☐ No ☒ If yes, by whom?
Yield gal/min. with ft drawdown after hrs

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test
Ballor test 0 gal/min. with 36 ft. drawdown after 4 hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? Yes ☐ No ☒

(10) WELL LOG:

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation

MATERIAL	FROM	TO
GRAVELY	0	7
HARD PAN	7	15
GRAVELY	15	48
CLAY	48	80
HARD PAN	80	138
FINE SOOPY SAND	138	144
WATER SAND M.I.K	144	149

Work started 19 Completed MAY 1988

WELL DRILLER'S STATEMENT:

This well was drilled under my jurisdiction and this report true to the best of my knowledge and belief.

NAME WHIDBEY DRILLERS (Person, firm, or corporation) (Type or print)

Address OAK HARBOR 98277

[Signed] Pearce John (Well Driller)

License No. 129 Date MAY 1988